

Proxicast

LAN-Cell 3

Firmware Release Notes

Release 5.2.0

Proxicast, LLC
312 Sunnyfield Drive, Suite 200
Glenshaw, PA 15116

1-877-77PROXI
1-877-777-7694
1-412-213-2477

Fax: 1-412-492-9386

E-Mail: support@proxicast.com
Internet: www.proxicast.com

January 31, 2013

Proxicast LAN-Cell 3 Firmware Release Notes

Date: January 31, 2013

Version:

ProxiOS Version: 5.2.0

Supported Hardware Platforms:

Proxicast LAN-Cell 3 (LC3-52U)

Supported USB Modems:

Modems are listed by their original equipment manufacturer and model name. Model names used by cellular operators may be different. Refer to the label on the modem or the documentation to determine if your modem is a rebranded version of a supported device.

Many USB modems from the same manufacturer have similar interfaces – unlisted modems may also function in the LAN-Cell 3 but have not yet been verified.

3GO		CGU-628	E1692
3GO11		CNU-680	E169G
Alcatel		D-Link	E176G
OT-X020		DWM-156	E169U
X220L		DWM-157	E170
A-Link		DWR-510	E172
3GU		Dupont / Toshiba	E1750
AMOI		BC2703	E1762
H01/H01A		G450	E176G
H02		EpiValley	E177
U2000		SEC-8089	E180
AnyData		Franklin Wireless	E182E
ADU-500A		U770 (Sprint) ¹	E219
ADU-510A		Huawei	E220
ADU-520A		B970	E226
Bandrich		E122	E270
BandLuxe C120		E1550	E353
BandLuxe C170		E156	E367
BandLuxe C270		E156G	E368
BandLuxe M300LC		E160	E600
BenQ		E160E	E612
U31		E160G	E620
C-Motech		E161	E660A
CDU-680		E169	E800

E960	Option	USB 306
EC1260	ICON 210	USB 308
EC156	ICON 225	Simcom
EC168C	ICON 401	5250
EC169	ICON 7.2	Solomon
ET168	GlobeSurfer HSUPA	S3Gm-660
K1550	GT Max 3.6	Sony Ericsson
K3715	Vodafone EasyBox	MD300
K3765	Vodafone K3760	MD400
K4505	Pantech	Toshiba
K4511	UM175	G450
T1731	UML290	Vibo
Hummer	Pro-Link	D200
DTM5731	PHS100	WinBest
iSonic	Qisda	HSDC-02
EDGE CARD	H21	ZTE
LG	Quanta	K3565-Z
LDU-1900D	MDO 588	MC2716
Maxon	Q101	MDC503UP
BP3	Q110	MDC505UP
BP3-EXT	Q111	MDC525UP
Neotel	Q120	MF620
NeoGo	Samsung	MF622/MF622 v2
Nokia	i9000	MF626
CS-11	GT-S8500	MF628
CS-12	SGH-Z810	MF628+
CS-15	Sierra Wireless	MF631
Novatel Wireless	AirCard 312U	MF633
4620L JetPack	AirCard 313U	MF636
5510L JetPack ²	AirCard 330U	MF636+
MC760	AirCard 595U	MF637
MC930D	AirCard 598U	MF638
MC950D	AirCard 875U	MF668
MC990D	AirCard 880U	MF668A
U679	AirCard 881U	MF820
U727	Compass 885	MH600HS
U760	Compass 888	MU351
U998	Compass 889	
USB551L	USB 305	

¹ Modem requires configuration prior to use in the LAN-Cell 3. See <http://support.proxicast.com> for more info.

² Modem does not support inbound initiated (remote access) connections.

Change History:

V5.2.0

- Added support for Virgin Mobile MC760 modem (variant of Novatel U760).
- Added support for tethered operation of the Novatel 4620L MiFi JetPack.
- Increased frequency of signal strength display updates when USB modem does not have an active data connection.
- Allow \$ () characters in password.
- Increased maximum length of DDNS hostnames to 128 characters.
- Increased maximum IPsec SA lifetime to 86400 seconds.
- Moved scheduled system restart timer function from Setup>Time to Admin>Management screen.
- Changed default system time zone to pure UTC (was GMT).
- Fixed issue causing static routing / IPsec conflict.
- Fixed issue with SNMP MIB causing some values to be returned incorrectly.
- Fixed PPTP client issue causing PPTP client to drop unexpectedly.
- Force IPsec to lookup remote gateway in DNS before every connection attempt when remote gateway specified as FQDN host.
- Corrected issue causing incorrect number of VPN connections to be displayed on status panel.
- Enable WiFi client to connect to access points which have spaces in their SSID
- Fixed issue with outbound ACL that affected packet denials.
- Force number of ports specified in Port Forwarding rules to match between external and internal interfaces.

V5.1.15

- Added support for the Bell Canada variant of the Sierra Wireless AirCard U330 modem.
- Increased aggressiveness of USB connection watchdog to include full system restart after repeated lockup detection.
- Improved initial display of modem signal strength on boot-up.
- Fixed DNS Server issue with DHCP-enabled Wi-Fi Guest LAN clients.
- Fixed DHCP Server issue limiting number of assignable addresses.
- Exempt LAN-Cell management port from DMZ when changed from 8080.
- Persist interface status changes made via Status Panel buttons across system restarts.
- Prevent backup routes from taking precedence over user-defined static routes.
- Increased maximum size of log entries.
- Enable newly added Virtual Host rules by default.
- Fix display issue on VLAN screen.
- Changed Wi-Fi Client Mode wording on WAN interface status.

V5.1.10

- Added software watchdog feature for USB-modems to detect reinitialization failures and other lock-up conditions.
- Fixed issue where Scheduled Reboot was not occurring based on count-down timer.
- Fixed compatibility issue with some Atheros-based Wi-Fi access points.
- Increased security of httpd daemon.
- Added support for D-Link modem: DWM157
- Added support for Huawei modems: EC156, E353, E367, K4511, T1731
- Added support for Novatel modems: U679 (LTE), U998
- Added support for Sierra Wireless modems: 312U (HSPA+), 330U (LTE)
- Added support for ZTE modems: MC2716 and MF668/MF668A

V5.1.0

Initial release to manufacturing.

Known Issues:

1. When in WAN Wi-Fi Client mode, the new SSID is not used when target SSID is updated in the GUI. Reboot to use the new target SSID.
2. When connecting a LAN-Cell 3 which has a private WAN IP address (e.g. 10.x.x.x from Verizon's LTE APN "vzwinternet" or AT&T's APN "broadband") to a remote IPSec VPN server, you must explicitly specify the Phase 1 Local and Remote ID values on both VPN devices; otherwise, the LAN-Cell 3 will send its WAN IP address as the default Local ID – this will not match the incoming IP address of the packet on the remote VPN Server. IP Addresses as well as Strings (e.g. DNS, E-Mail) are supported for Phase 1 ID's. If the LAN-Cell 3 has a private WAN IP address, it must also initiate all VPN connections with the remote VPN Server (enable Connection Initiation on the VPN rule popup screen).
3. The Pantech UML290 modem sometimes does not display signal strength when first initialized. Disable and re-enable the USB interface to enable signal strength display.